



TECHNICAL INFO N° 4

ULTRA-DESTRUCTIBLE FILM

1. INTRODUCTION

Considering the technical properties in terms of ultra-destructibility of that product, care must be taken during all handling steps.

2. CONVERTING ADVICES

- We recommend :
- a as slow as possible converting speed (< 20 m/min).
 - a as slow as possible web tension.
 - the use of a state of the art die-cutting tool (sharp, no adhesive residue).
 - a low matrix stripping angle (under 90° in any case).

MATRIX STRIPPING

